



Description

Stabilized High-Current 5V/2.4A power net adapter with USB A connection.

Note: use the USB cable that came with your scanner, or order necessary cable separately.

Features

Properties

Serie(s): OPN-3102 OPN-3002 OPN-2001 OPN-2006 OPN-4000

Physical

Connection(s): USB-A

Labels

Quality Seal: Approved!